



## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
1	1	1.0	Interface	<b>to be created!</b>	... is there still no notion of a drop-down list (like EXCEL)?
2	2	1.0	Interface	-	... he doesn't master the MASCULIN - WOMAN genre? Example: choose the default template file for RAPNOUV = none? In the dimension styles, the tolerances propose for METHOD: NO (E) proof that he does not know!!!! It's NO method of course!
3	3	1.0	Interface	-	... does he check and analyze the link files .LNK (windows shortcut) and especially if the link no longer exists, he displays a window? Proof that data is being read unnecessarily! And then we are surprised that some drawings put a "lead" to open?
4	4	1.0	Interface	-	... sometimes while making ESC. the AutoCAD window is disabled, nothing is missing when you type? Click on the AutoCAD window to reactivate it! This often happens after unrolling a MENU, choosing a command, then ESCAP. !!!!
5	5	1.0	Interface	-	... when several drawings are opened (drawings A, B, C, D = order of the file tabs) and I am for example in drawing B (2nd file tab) from which I open an XREF that it contains, I modify it, I save it and close it... And AutoCAD returns to the tab of the last file, the drawing D!!!! If we are not careful, we risk making mistakes!
6	6	1.0	Interface	-	... the control line cannot be adjusted in line height when it is anchored at the top of the screen?
7	7	1.0	Interface	-	... when installing AutoCAD, the setting of WORK SPACE PARAMETERS is on the option DO NOT SAVE WORK SPACE?
8	8	1.0	Interface	-	... do not translate more simply the insertion drop-down menu proposes: REFRENECE D'IMAGE RASTER instead of : Image?
9	9	1.0	Interface	-	... when you have changed applications via the Windows taskbar and want to return to AutoCAD, sometimes it doesn't work because of a window opened in AutoCAD, such as options, or others?
10	10	1.0	Interface	-	... still exists the REDESS command in the DISPLAY drop-down menu? We are very far from the years when it was common to wait 2-3 minutes after a REGEN, when the REDESS was instantaneous!!!!
11	11	1.0	Interface	<b>MENU</b>	... do not translate more simply the insertion drop-down menu proposes: INSERT Layer UNDER JACENT PDF instead of : PDF file?




## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
12	12	1.0	Interface	Windows	... the window: ECHELIST LIST is still not adjustable?
13	13	1.0	Interface	Windows	... the window: TEXT STYLE is still not adjustable?
14	14	1.0	Interface	Windows	... the window CHOICE OF THE LINE TYPE of the layers command, is not adjustable?
15	15	1.0	Interface	Windows	... to have refined some scrollbars as much as possible, such as in the tool palettes, the PROPERTY window?
16	16	1.0	Interface	Windows	... to close some windows, you have to look for the cross sometimes on the top right, sometimes on the top left?
17	17	1.0	Interface	Text Window	... the display of the TEXT window (F2) does not correctly handle a line break? Example with a LISP instruction: (entget(entlast)) !!!!
18	18	1.0	Interface	Layout	... since 2015, it is no longer possible to change the PRESENTATION if an order is in progress? It is necessary to make ESCAP....
19	19	1.0	Interface	Layout	... why, since 2015, do not you have to "tremble" to copy a presentation with the CONTROL key? You have to stay on the presentation tabs and if you move too far away the copy becomes impossible!!!!
20	20	1.0	Interface	Layers	... the Layer Running window does not allow you to ZOOM when it is active?
21	21	1.0	Interface	Layout	... have deleted the arrows for managing the scrolling of presentations (such as EXCEL)?
22	22	2.0	Interface	Sélection CYCLING	... the CYCLIC SELECTION window is not adjustable?
23	23	2.0	Interface	Sélection CYCLING	... the CYCLICAL SELECTION window does not display the Layer NAME next to the objects displayed in the window? It is necessary to follow the name of the layer at the top in the drop-down list of layers at the same time as scrolling through the CYCLICAL SELECTION list !!!!
24	24	2.0	Interface	Sélect SIMILAR	... in the parameters window of the similar selection, isn't there a button ALL SELECT / ALL DESELECT?
25	25	1.0	Interface	List POPUP	... is it not possible to adjust the width of some drop-down lists such as : LIST OF LIMITS, TEXT STYLE, COAST STYLE, etc.? Whether in CLASSIC or TAPE mode!!!!




## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
26	26	1.0	Interface	<b>Taskbar</b>	... did the RESOL and GRID buttons disappear from the taskbar when you are in the PAPER area?
27	27	1.0	Interface	<b>System Variables</b>	... fortunately I don't use the TAPE! But why, in RIBBON mode, some messages continue to appear when the system variable EXPERT = 2 and even if = 5? Example with the current layer is INACTIVE! In RIBBON mode the message is displayed, but never in classic mode!
28	28	1.0	Interface	<b>Objet snap</b>	... since 2005, still no icon (nor image) for the hanging BETWEEN 2 POINTS in the hanging toolbar? No image for this snapshot in the context menu with SHIFT - Right mouse button!
29	29	1.0	Interface	<b>Objet snap</b>	... since 2016, still no icon for GEOMETRIC CENTER hanging in the hanging toolbar?
30	30	1.0	Interface	<b>RENAME</b>	... the rename command, heading BLOCK, does not display the BLOCK icon?
31	31	1.0	Interface	<b>Scale list</b>	... it is not possible to select all scales in the ECHELIST LIST window by doing a CONTROL + A ?
32	32	1.0	Interface	<b>Windows</b>	... the window to choose a folder, reverse the sorting of the character _ (underscore) it is at the end of the list? Example choice of a folder in the options: Files tab....
33	33	1.0	Interface	<b>Windows</b>	... the window: LINE THICKNESS SETTINGS still not adjustable? While at the end of 2016, it was said that "all" windows were adjustable!
34	34	1.0	Interface	<b>Windows</b>	... The window to load applications is not in a STANDARD format with the shortcuts on the left, like the windows: Open, Save As, Export, etc.?
35	35	1.0	Interface	<b>Windows</b>	... in some windows that propose to reorganize the lines, dragging is not possible and it is necessary to use the buttons, "of another age", MONTER-DESCENDRE? Example: BLOCK ATTRIBUTOR MANAGER!
36	36	1.0	Interface	<b>Windows</b>	... when creating POLYGONAL WINDOWS and OBJECTS the SCU icon is always OFF?
37	37	1.0	Interface	<b>DESIGN CENTER</b>	... when opening the DESIGN CENTER the tab activated at the top, is FOLDED while the displayed view corresponding to DESIGN OPEN?
38	38	1.0	Interface	<b>XREFS</b>	... these misguided verbs for the management of XREFS: UNLOAD and UNLOAD which are very similar? Why not just: INACTIVE and DELETE?




## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
39	39	1.0	Interface	FIELD	... the FIELDS command does not offer a standard command as for INSERT (= _INSERT), CALQUE (= _LAYER)? Which PROHIBITS any MACRO with this command!!!!
40	40	1.0	Interface	FILTER	... the FILTER command does not offer a standard command as for INSERT (= _INSERT), CALQUE (= _LAYER)? Which PROHIBITS any MACRO with this command!!!!
41	41	1.0	Command	Windows	... if a window is created from a polyline obtained by the CONTOUR command, the window is not activated and nothing is displayed in the window when switching to the object space of the window? REGEN is inoperative and only after a REGENER ALL the objects are displayed!!!!
42	42	1.0	Command	Layers	... can't we still COPY-COLLATE a layer and rename it quickly?
43	43	1.0	Command	Layers	... the XREF layer filter does not keep the option to invert the ACTIVE filter when the file is reopened?
44	44	1.0	Command	Layers	... why isn't the checkbox to reverse the filter located at the top of the window?
45	45	1.0	Command	Layers	... for the creation of a "Pre-Frozen" layer, the icon displays this incomprehensible name: NEW FREEZE Layer WINDOW IN ALL WINDOWS??? Why not just: New layer frozen in all windows!
46	46	1.0	Command	Layers	... can't we reduce the width of the window BREAK LIMITS more than that?
47	47	1.0	Command	Layout	... the _LAYOUT or PRESENTATION command does not allow to manage the position, the order of one or more presentations?
48	48	1.0	Command	Layers	... the bubble to cancel the isolation of the layers proposes as command name: ASSOCIATE Layers? CANCELLING THE ISOLATION OF LOCKS would be more appropriate!!!!
49	49	1.0	Command	Attach by layer	... the ATTACH BY Layer window (3D material management) offers a very curious ranking of the list of layers? At the beginning the names of the layers in CAPITAL LETTERS, then the names of the layers in MINUSCULES ????????????????????
50	50	1.0	Command	New	... AutoCAD does not display a version incompatibility message when creating a drawing with a higher version template? AutoCAD simply creates a new blank drawing from a standard template in the TEMPLATE folder!
51	51	1.0	Command	RECOVER	... following the RECUPER command, if errors are indeed corrected and the drawing is closed without saving it AutoCAD leaves the drawings without saving it and without sending the message: Do you want to save?




## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
52	52	1.0	Command	Line Type	... despite my ticket N° 14174957, subject reported to Cas Salesforce on April 27, 2018 by sachin_psi. (Folder status = Open), there is always this type of line AXES2 which no longer exists in the files .LIN : ACADISO, ACADLTISO, ACAD and ACADLT and it is always CENTER2 which appears? Ditto for the German, Italian, Portuguese, etc. versions!
53	53	1.0	Command	PROPERTIES	... the PROPERTIES command (window), still does not allow to modify the LENGTH and ANGLE of a line?
54	54	1.0	Command	PROPERTIES	... when you are on a SCU, the PROPERTY command displays the rotation angle of the objects with respect to the General SCU and not the current SCU?
55	55	1.0	Command	PROPERTIES	... is there still no drop-down list for transparency in the PROPERTIES command and in the TOOLS of the tool palette?
56	56	1.0	Command	RENAME	... to rename a BLOCK the RENAME command is still as archaic as when it was released in version 12 (in 1991, I think)?
57	57	1.0	Command	Group	... the full versions would not benefit from the GROUP MANAGER command of the LT version, which is much more "user-friendly"?
58	58	2.0	Command	Group	... the group manager of the LT version does not display the *A groups while the box: include nameless groups, is checked? It is necessary to uncheck each time then, to recheck to make them appear....
59	59	1.0	Command	POLYLINE	... the arc does not have the same meaning as the segments when you break down a POLYLINE with ARCS and JOIN, the arc has a different meaning when you REVERSE the polyline? This is very problematic with a line type that includes an arrow!
60	60	1.0	Command	RECTANGLE	... after 37 years, we still do not know how to "create-modify" a RECTANGLE with the notions of LENGTH - WIDTH?
61	61	1.0	Command	CHAMFER	... the chamfer control no longer works with the angle option, when in units the HOURLY SENSING option is checked?
62	62	1.0	Command	CHAMFER	... the chamfer command displays the default angle in RADIANS when the ANGLE option is selected again?
63	63	1.0	Command	HATCH	... the size of the icons representing the hatching is also RiKiKi? Especially those in the OTHER PREDEFINITE tab!
64	64	2.0	Command	TRIM	... the ADJUST command does not allow to delete a "NOT ADJUSTABLE" segment as with INVENTOR?




## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
65	65	1.0	Command	STRETCH	... this message "curious when using the command ETITRATE : Choice of objects to stretch by capture window ! Window - capture is rather contradictory? Or simply: Choice of objects to stretch by capture?
66	66	2.0	Command	ARRAY	... talk about SPACEMENT instead of AXIS ENTER for the columns and rows of the RESAU command?
67	67	1.0	Command	SINGLE LINE TEXT	... is it impossible to use the SPACE when writing text with the SHIFT key pressed?
68	68	1.0	Command	DESIGN CENTER	... the DESGIN CENTER displays some SINGLE BLOCK icons upside down while if you check the preview of this block it is oriented correctly?
69	69	1.0	Command	ATTDEF	... the window for creating ATTRIBUTES always offers the option CHECK? it is TOTALLY OBSOLETE!
70	70	1.0	Command	WMF Insert	... following a WMF export, then the insertion of this WMF, there is a change of scale according to the ZOOM in progress?
71	71	1.0	Command	XREFS	... is there no warning message when trying to REMOVE an XREF that is on a LOCK LOCK?
72	72	2.0	Command	XREFS	... the window to insert an XREF does not offer the INSERT option on the SCG or SCU?
73	73	2.0	Command	XREFS	... does the list of XREFS scales systematically pollute and overload the list of scales of the current drawing? And this since the arrival of the anotative....
74	74	2.0	Command	FIELD	...when using the OBJECTS field by selecting a PRESENTATION WINDOW and the property: SCALE NAME, AutoCAD often displays the calculated value instead of the NAME as requested, example 1/50 displays 20 (for a drawing in Metre scale list: 1/50 = 1000/:50
75	75	1.0	Command	FILTER	... the FILTER command is not up to date, because it does not provide a list of all current objects? Example when there are AEC objects, PROXY the FILTER command does not find them!
76	76	1.0	Command	FILTER	... the filter name is limited to 19 characters when you register a filter in the FILTER? command.
77	77	1.0	Command	Plot	... the plot banner does not print when using automatic publication?



## 112 Questions, Why AutoCAD... ??? ...


N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
78	78	1.0	Command	Plot	... since the 2005 version, when you uncheck CENTER TRACE, the X and Y parameters do not automatically return to 0.0?
79	79	1.0	Command	Plot	... have created the PORTRAIT and LANDSCAPE plot formats for AutoCAD PDF printers, while there are PORTRAIT and LANDSCAPE BUTTONS? Which unnecessarily pollutes this list, which is now doubled!!!!
80	80	1.0	ANNOTATIVE	SINGLE LINE TEXT	... a simple text justified in the ENVIRONMENT and using an ANNOTATIVE text style with the option "Matching the orientation of the text to the presentation" is justified at least when modifying the SCU?
81	81	1.0	ANNOTATIVE	ATTRIBUTE	... the handles of the ATTRIBUTES are totally unmanageable on ATTRIBUTES using an ANNOTATIVE text style with the option to match the orientation of the text to the presentation?
82	82	1.0	Dimension	Multi Leader	... this incomprehensible tooltip: PLACE THE CONTENT (TEXT) OF THE MULTIPLE REPEATING LINE IN A TEXT AREA? All this to say ACTIVATE THE FRAME of the multi-line text in the style of the line of reference, tab: CONTENT!!!
83	83	1.0	Blocks	RENAME	... wouldn't the DESIGN CENTER, the BLOCK EDITOR allow you to rename a BLOCK?
84	84	1.0	Blocks	Blocks Palett	... propose the RECENT BLOCKS tab in the new BLOCKS palette? I think it's "dangerous"! If I am not careful, I may insert a similar block that has nothing to do with the block in the personalized LIBRARY!
85	85	1.0	Blocks	Make block	... the CREATE BLOCK command displays a preview of the entire RiKiKi BLOCK? While the DESCRIPTION area, which is practically NEVER filled in, is huge?
86	86	1.0	Blocks	WBLOCKS	... when exporting a block via the WBLOC command, it is the unit of the drawing that will be assigned to the exported file and not the unit of the BLOC?
87	87	1.0	Blocks	ATTEXT	... has the ATTEXTR command not been updated since the appearance of the DYNAMIC BLOCKS (version 2006)? All BLOCKS have the same name = *U
88	88	1.0	Attributes	ROTATE	... ATTRIBUTES "flip a switch" when rotating a block with a user SCU?



## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
89	89	1.0	Attributes	ATTDEF	... this most incomprehensible translation in the window for creating ATTRIBUTES, in the bubble that explains the PREDEFINI option: WITHDRAWAL THE DEFAULT VALUE OF THE ATTRIBUTES WHEN INSERTING A BLOCK CONTAINING A PREDEFINI ATTRIBUTES? Youaaaaaaaa! All this to explain that this block will be inserted without displaying the request for attributes!!!!!! And provided that all attributes are PREDEFINED!!!!!!
90	90	1.0	Attributes	Edite attribute	... can't the value of the ATTRIBUTES be entered on the line of the attribute concerned instead of going down in the VALUE field, in the window ATTRIBUTES EDITOR AND EXTENDED !
91	91	1.0	ToolPalettes	Interface	... is it not possible to export and import several tool palettes?
92	92	1.0	ToolPalettes	Interface	... persist in offering this MECHANICAL toolbox with an absolutely lamentable representation of the SCREWS?
93	93	1.0	ToolPalettes	Interface	... the TOOL PROPERTIES window of a tool in the tool palette does not keep the size setting of the left area? Indeed, when you enlarge the window and reduce the left zone to 1/10th, if you leave and return, the width of the left zone takes 1/3 of the overall width!
94	94	1.0	ToolPalettes	Interface	... the customize palettes window does not allow you to adjust the left area (palettes)?
95	95	2.0	ToolPalettes	Interface	... the LEFT ZONE (list of palettes) of the TOOL PALLET CUSTOMIZATION window is not adjustable?
96	96	2.0	ToolPalettes	Interface	... the list does not move when you want to move up a TOOL PALLET in the list of the PALETES CUSTOMIZATION window and the list is very long!!!!
97	97	2.0	ToolPalettes	Interface	... when renaming the tab of a tool palette, the name is always hidden, you have to move with the arrows on the keyboard?
98	98	2.0	ToolPalettes	Interface	... when you want to reorganize the palettes in the customization window, the list does not move automatically when you have several pages?
99	99	1.0	ToolPalettes	Interface	... in the customize tool palettes window, the left area is not adjustable?
100	100	1.0	ToolPalettes	Annotative	... a tool in the tool palette that uses an ANNOTATIVE COAST STYLE creates the STYLE in the current drawing, if it does not exist, but does not make it ANNOTATIVE?





## 112 Questions, Why AutoCAD... ??? ...

N°	REF	Version	Domain (EN)	Command (EN) ou Concerns E(N)	Why...? ... (EN)
101	101	1.0	ToolPalettes	HATCH	... the hatches created from the tool palettes do not keep the ANNOTATIVE option?
102	102	1.0	ToolPalettes	Blocks	... the blocks inserted from the tool pallets do not have a repeat option like the 2020 block pallet?
103	103	2.0	ToolPalettes	Blocks	... the INVITE TO ENTER A ROTATION option is always by default set to NO (tool PROPERTIES window)? Whereas for the majority of blocks, you need a ROTATION?
104	104	1.0	ToolPalettes	Blocks	... can't blocks with different X Y Z scales be inserted from the tool pallets?
105	105	1.0	ToolPalettes	Blocks	... having reinvented a pallet of blocks instead of perfecting the tools of the tool pallets?
106	106	1.0	ToolPalettes	Blocks	... the image of an ANNOTATIVE BLOCK is not displayed when dragging it onto a tool palette and the DISPLAY ANNOTATION OBJECTS icon is OFF (KUTCH icon with the circle)?
107	107	1.0	ToolPalettes	Blocks	... not allow to PRE-FILL attributes from the BLOCK insertion tools into the TOOL PALETTES, see the block palette, a bit like the parameters of dynamic blocks?
108	108	1.0	System Variables	-	... the DTEXTED system variable was deleted from 2018 and curiously the TEXTED system variable was created with the 2010 version (I think)?
109	109	1.0	System Variables	-	... the system variables USERi..., USEIRr and USERS.... stops at 5 variables? Since time immemorial, why not allow them to be freely created? The Post Office's memory is no longer a problem!
110	110	1.0	System Variables	-	.... USERS system variables.... does not exist in LT versions?
111	111	1.0	System Variables	-	... if the system variable OLEFRAME = 0, it is impossible to select this OLE object without having to modify the value of OLEFRAME by setting 1 or 2? While for images, PDFs no problem if the value is 0 (IMAGEFRAME, PDFFRAME)?
112	112	1.0	System Variables	SETVAR	... the list of system variables displayed with the MODIFVAR command is not sorted alphabetically?